



PUBLIC WORKS DEPARTMENT

AN ISO 9001-2008 CERTIFIED DIVISION

No: AEE/No.1 Bld Sub Dvn/V.V, Centre /2026-27/149

Dated: 10/6/2026

ANNEXURE-D

BUILDING SAFETY CERTIFICATE


Certified that the existing building **Gurushree Vidya Kendra, (Gurushree Education Society)**, No. 31/2, Doddabidarakallu, Nagasandra Post, Bangalore - 560073. Is having Block (s) Floor (s) as per details given below:

Details of Block(s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)
No. of Floors (s) in the Block	G+4	G+3	G+2		

The Building is owned/occupied by **Gurushree Vidya Kendra, (Gurushree Education Society)** have complied with the Building Safety requirements as per submitted testing reports and verified by the officers concerned of **Karnataka Public Works Department** on **03-06-2026** in the presence of Consultant Engineer, **Sri. Rajaram** and that the building/ premises is fit for occupancy for running school for a period from date: 10-06-2026 to 09-06-2027 of **one** year in accordance with rule and subject to compliance of the specific conditions as appended.

1. Dampness was observed in washroom areas.
2. Minor hairline cracks were observed at some portion of the buildings.

Issued on: 10-06-2026 at Bangalore.


Assistant Executive Engineer,
No.1 Building Sub-Division,
V.V Tower, Bengaluru.